

902 Absolute Piezo Transducer Compact Pressure Sensor Pin-outs

Pin	Description
1	Relay NO
2	Relay NC
3	Power (+)
4	Power (-)
5	Analog Output (+)
6	Relay Common
7	RS485 (-)
8	Analog Output (-)
9	RS485 (+)