
## 953 Pirani/Cold Cathode Vacuum Sensor System Pin-outs

## 15-pin Accessory Connector



Pin	Description
1	Pirani Set Point Relay 1 - Normally Closed Contact
2	Pirani Set Point Relay 1 - Common
3	Pirani Set Point Relay 1 - Normally Open Contact
4	Cold Cathode Set Point Relay 2 - Normally Closed Contact
5	Cold Cathode Set Point Relay 2 - Common
6	Cold Cathode Set Point Relay 2 - Normally Open Contact
7	Not Used
8	Not Used
9	High Voltage Disable
10	Pirani Analog Output
11	Cold Cathode Analog Output
12	Ground
13	Ground
14	Pirani - Cold Cathode Switchover Disable
15	Pirani - Cold Cathode Switchover Disable